

Montrose Public Lands Center Warehouse Improvements – Supplementary Site Pictures

Site pictures are provided to supplement the drawings and specifications.



Warehouse Building – Looking North



Inside warehouse looking south




Inside warehouse, looking north



Inside warehouse – looking south.

Montrose Public Lands Center Warehouse Improvements – Supplementary Site Pictures



Warehouse overhead door to be replaced.



Warehouse sprinkler head near garage door track



Warehouse – proposed utility sink, eye wash station, and plumbing repair.




Inside warehouse – looking north

Montrose Public Lands Center Warehouse Improvements – Supplementary Site Pictures




Electrical Panel



Electric outlet to be relocated.



Approximate location of proposed electric receptacles



Existing electric receptacle

Montrose Public Lands Center Warehouse Improvements – Supplementary Site Pictures



Typical warehouse luminaires – to be replaced.



Typical office and bathroom luminaires – to be replaced.





Approximate location of proposed luminaries




Office 3 sink, countertop, and shelf to be demolished.



Men's bathroom – women's similar



Women's bathroom – men's similar



Proposed bathroom door.

Montrose Public Lands Center Warehouse Improvements – Supplementary Site Pictures



Rooftop HVAC unit – to be replaced.



Warehouse Door Closer – to be replaced

Montrose Public Lands Center Warehouse Improvements – Supplementary Site Pictures




Warehouse Roof




Warehouse Roof



Warehouse Roof



Warehouse Roof



Screw holes in warehouse roof.



Screw holes in warehouse roof.

Montrose Public Lands Center Warehouse Improvements – Supplementary Site Pictures




Roof leak – wet spot of floor is a roof leak.



APPROXIMATE LOCATION OF ROOF LEAK

Approximate location of roof leak

Montrose Public Lands Center Warehouse Improvements – Supplementary Site Pictures



Storage Shed – Manually operated overhead doors



Photovoltaic Inverter – to be replaced.